

- Branson -

	Type	L #	Hits	Search Text	DBs	Time Stamp
1	BRS	L2	239	I1 and coupler	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/27 11:33
2	BRS	L3	0	I2 and superconductor	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/27 10:52
3	BRS	L4	0	I1 and superconductor	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/27 10:53
4	BRS	L5	347	333/99s.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/27 12:15
5	BRS	L6	27	I5 and coupler	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/27 11:06
6	BRS	L1	356	333/109.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/27 11:26
7	BRS	L7	36	I2 and detector	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/27 11:34
8	BRS	L8	235	505/210.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/27 12:56
9	BRS	L9	504	333/116.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/27 12:57